

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

KTC'S NECT PUBLIC SCHOOL CHERUVATIPUR  
CHERUVATIPUR, KOTHAMANGALAM.

GF-30.80 X 6.50 X 3.60 RCC ROOF  
FF-18.30 X 5.20 X 3.60 "  
F.F-37.40 X 6.50 X 3.60 "  
S.F-18.30 X 5.20 X 3.60 "  
S.F-37.40 X 6.50 X 3.60 Sheet Roof  
F.F-18.30 X 5.20 X 3.60 Sheet Roof  
Academic year 2023-2024

5. Period for which the certificate is issued
6. Nature of defects , if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and Windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly

} RCC

} 1/0

} YES  
The structure is sound under normal wind and weather conditions

9. Whether the structure is sound or not for conducting classes

**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate. *Fitness is issued for year 2023-24 of following conditions*  
 False Ceiling or PVC Ceiling Should be done before next year and for facilities should be done. CERTIFICATE

certified that the school building was inspected by me on 13/06/23 and found to be fit / ~~unfit~~ to conduct classes, for the period Academic year 2023-24 for the reasons stated above.

Place: NELLIKUZHI.  
Date: 13/06/23



*[Signature]*  
**Assistant Engineer**  
**LID & EW Section**  
**Nellikuzhi Grama Panchayat**

Assistant Engineer